

Associated Fire

Protection (NI) Ltd

Unit 5, Warrenpoint Enterprise Centre. Newry Road. Warrenpoint. Co.Down, BT34 3LA | 028417 54499 | sales@afpni.com

Carlingford Lough Yacht Club Killowen Point, Rostrevor Co.Down **BT34 3AN**

Invoice Number Invoice Date

INV-27697 29 Sep 2021

Reference / Order Number **Payment Due Date:**

20 Oct 2021

Description	Quantity	Unit Price	VAT.	Amount GBP
Basic Annual Fire Extinguisher Inspection & Certification	1.00	39.00	20%	39.00
Individual Extinguisher Service to BS 5306	7.00	2.50	20%	17.50
			Total Net Amount	56.50
			Total VAT 20%	11.30
		F	Invoice Total GRP	67.80

Account No. 69637252 Sort Code 08-92-99 Paypal: sales@afpni.com

Registered in Northern Ireland-Company No. NI619325 Vat Registration No. 166120530

Fire Extinguishers Fire Alarms

Fire Risk Assessment Staff Training Emergency Lighting | Portable Appliance Testing Fire Safety Signage | Fire Safety Products









ASSOCIATED FIRE PROTECTION (NI) LTD

Fire Extinguishing Equipment Inspection and Servicing Report

Details of the clien	t de la companya de
Name:	Carlingford Lough Yacht Club
Address:	Killowen Point, , Rostrevor, Co.Down, BT34 3AN
Date Issued:	29/09/2021
Next Test Due:	29/09/2022
Technician:	Michael Mitchell

Quantity	Туре	Basic Service	Extended Service	Refill	Commissioned	Condemned
	<u></u>	(B)	(E)	(R)	(C)	
3	Water	3	0	0	0	0
0	Foam	0	0	0	0	0
4	CO2	3	0	0	0	0
0	Powder	0	0	0	0	0
0	Wet Chemical	0	0	0	0	0
0	Hose Reels	0	0	0	0	0
1	Fire Blankets	1	0	0	0	0

Certification of Inspection and Servicing

On the date this certificate was issued, apart from any non-conforming extinguishers as recorded, all portable fire extinguishers have been maintained in accordance with BS5306-3

Additional Notes

D. Additional Information / Recommendations

Do all extinguishers comply with current legislation?

Is the quantity of equipment provided adequate for the above premises

Has the technician been given access to the most recent fire risk assessment?

N/A

Has the customers logbook been signed?

N/A

Has the technician been given access to the client's asbestos register?

N/A

Has the client been issued with a Waste Disposal Notice?

Clients Signature



Details of Servicing the Available Fire Extinguisher Equipment

Item no.	Asset ID	Location	Item / Action	Next ES	Notes
1		Front Entrance	6 Litre Water - Basic Service		
2		Switch Board	2 KG CO2 - Basic Service		
3		Kitchen	2 KG CO2 - Basic Service		
4		Kitchen	Fire Blankets - Basic Service		
5		Bar Store	2 KG CO2 - Basic Service		
6		Club Hall	9 Litre Water - Basic Service		
7		Club Fire Place	9 Litre Water - Basic Service		
8		Boat House	2 KG CO2 -		No Access